




# Sierra Components, Inc.

2222 Park Place, 3-E • Minden, Nevada 89423  
Phone: 775.783.4940 Fax: 775.783.4947



| PAD | FUNCTION        |
|-----|-----------------|
| 1   | B1              |
| 2   | B0              |
| 3   | C1              |
| 4   | C <sub>N</sub>  |
| 5   | C0              |
| 6   | $\overline{E}$  |
| 7   | V <sub>EE</sub> |
| 8   | GND             |
| 9   | S2              |
| 10  | S1              |
| 11  | S0              |
| 12  | A0              |
| 13  | A1              |
| 14  | A <sub>N</sub>  |
| 15  | B <sub>N</sub>  |
| 16  | V <sub>CC</sub> |

**Topside Metal: (AL)**  
**Backside Metal: (Si)**  
**Backside Potential: Vcc or Float**  
**Bond Pad Size: .004" x .004" min**  
**Mask Ref:**

**APPROVED BY: MG**

**DIE SIZE: 55 x 57**

**DATE: 11/3/16**

**MFG: Texas Instruments**

**THICKNESS:**

**P/N: CD74HC4053**