




# Sierra Components, Inc.

2222 Park Place Building 3 Suite E • Minden, Nevada 89423  
 Phone: 775.783.4940 Fax: 775.783.4947



PAD	FUNCTION
1	Vcc
2	HIN1-
3	HIN2-
4	HIN3-
5	LIN1-
6	LIN2-
7	LIN3-
8	FAULT-
9	ITRIP
10	CAO
11	CA-
12	VSS
13	VSO
14	L03
15	L02
16	L01
17	N/A
18	VS3
19	HO3
20	VB3
21	N/A
22	VS2
23	H02
24	VB2
25	N/A
26	VS1
27	H01
28	VB1

**Topside Metal: Aluminum**  
**Backside: Silicon**  
**Backside Potential:**  
**Mask Ref:**  
**Bond Pads: .004" Minimum**

<b>APPROVED BY:</b>	<b>DIE SIZE: .127" X .179"</b>	<b>DATE: 6/30/00</b>
<b>MFG: IRI</b>	<b>THICKNESS: .026"</b>	<b>P/N: IR2132</b>

DG 10.1.2  
 Rev A 3-4-99