




Sierra Components, Inc.

2222 Park Place Building 3 Suite E • Minden, Nevada 89423
Phone: 775.783.4940 Fax: 775.783.4947



Topside Metal: Aluminum
Backside Material: TiNiAg
Backside Potential: Drain
Bond Pad Size: .004" Min.
Mask Ref:

APPROVED BY: DG

DIE SIZE: .170" x .225"

DATE: 10/20/04

MFG: Motorola

THICKNESS: .016"

P/N: IRFC9140