




# Sierra Components, Inc.

2222 Park Place Building 3 Suite E • Minden, Nevada 89423  
 Phone: 775.783.4940 Fax: 775.783.4947



| <u>PAD NO</u> | <u>FUNCTIONS</u> |
|---------------|------------------|
| 1             | Output 1         |
| 2             | Input 1-         |
| 3             | Input 1+         |
| 4             | V-               |
| 5             | Input 2+         |
| 6             | Input 2-         |
| 7             | Output 2         |
| 8             | V+               |

NOTE: SUBSTRATE MAY BE CONNECTED TO -V SUPPLY OR MAY BE LEFT FLOATING.

**Topside Metal: Aluminum**  
**Backside: Silicon**  
**Backside Potential: See Above**  
**Mask Ref:**  
**Bond Pad Size: .004 ± .0003**

|  |  |  |
|--|--|--|
| <b>APPROVED BY:</b><br><b>MFG:Harris Semi.</b> | <b>DIE SIZE: .054" X .103"</b><br><b>THICKNESS: .014 ± .003"</b> | <b>DATE: 8/10/01</b><br><b>P/N: HAO-5142</b> |
|--|--|--|